

30

300

Preformed basic inframe overhaul, new oil, oil filters, antifreeze.. When we pulled #5 piston skirt it was broke in half, We are sending it in for core, if it doesn't core customer will then be charged the core. We also had to reuse the bottom shell on #6 main, it is no longer available, advised owner of this. Replaced both

TRK # 02 / Mileage: 491182

headlight bulbs

Due at time of service, Anything over 30 days will by charged 1.5% late fee

PAYMENT

Due at time of service, Anything over 30 days will by charg