

EARTH EQUIPMENT

EARTH EQUIPMENT

ITEM NO	-	# 251
MAKE	-	TAKEUCHI
MODEL	-	TL 10
S/N	-	201002201
PRICE	-	\$58,000.00
PURCHASE DATE	-	3/21/2016
VENDOR	-	LUBY
WEIGHT	-	

TRANS

T MAKE	-	
T MODEL	-	
T S/N	-	
T SPEC	-	

TIRES

FRONT SIZE	-	
REAR SIZE	-	
AIR PSI	-	

BATTERY

GROUP	-	
QTY	-	

BELTS

ALT	-	
COMP	-	
WATERPUMP	-	
FAN	-	
HYD	-	
OTHERS	-	

REPAIRS NEEDED

ENGINE

E MAKE	-	KUBOTA
E MODEL	-	V3800T
E S/N	-	2EY2305
CODE	-	1J301-1100
FUEL TYPE	-	DIESEL

LUBRICATIONS

ENGINE OIL	-	15W 40 13.9 qts.
TRANS OIL	-	
HYD OIL	-	10W 30 19.5 gals.
PLANTARY	-	
DRUM OIL	-	
BRAKES	-	
STEERING	-	

FILTERS

ENGINE	-	KIC020-32430
TRANS	-	
HYD	-	1511-0100 or 57887wix
FUEL	-	16631-43560 & AFKIJ301-43170
AIR	-	19111-13001 & 1911113002
FUEL OTHER	-	RD451-51940
CAB	-	19115-08311 & 19115-06052

NOTES

REPAIRS

HOURS	
10	3-21-16 got all numbers and installed KCI stickers also painted on #251 installed GPS
251	10-5-16 Serviced, pressure washed, cleaned out radiator
565	3-22-17 Serviced, checked all fluid levels
968	8-14-17 Serviced cleaned out radiator, checked all fluid levels
987	8-17-17 new tracks
1100	10-27-17 Serviced, pressure washed radiator, checked all fluid levels
1149	11-28-17 pressure washed, checked all fluid levels, new head light on rear, repaired door latch
1280	3-6-18 Serviced, all filters, pressure washed, checked out
1349	5-14-18 drill welded down on quick attachment plate
1406	5-29-18 replaced front right roller
1446	6-8-18 repaired quick attachment dowl pin
1548	7-9-18 replaced both tracks
1900	1-11-19 serviced air oil fuel
2055	4-6-19 Replaced fuel line from rail to head, new antifreeze, rebuilt bucket cyl, installed Cat Tracker and fire ext. Replaced shocks on door. Tracker SN:2163165144
2151	4-3-19 serviced air oil fuel and cab changed finals
2244	4-25-19 replaced blower motor and hydraulic couplers
2285	6-5-19 weld new pivot pin on bobtach
2438	9-4-19 replaced ac belt
2488	10-3-19 put door glass and frame in
2477	10-10-19 Replaced Tracks on Dorset job
2582	9-27-19 serviced air oil fuel cab and finals tighten belts
2788	11-1-19 service air oil fuel cab replaced battery
2850	3-10-20 replaced cab shocks and mounts
3089	5-7-20 serviced air oil fuel cab and finals
3180	10-20-20 Serviced, changed all filters on machine, 2 new cab shocks, 2 new tracks, 2 new shocks on front glass, greased, removed air cleaner box and cleaned out all the dirt, put wear plate on bottom of bucket, welded cracks in bucket.
3334	12-28-20 Check out, replaced both front headlights, left rear back up light
3384	3-10-21 serviced air oil fuel cab and replaced both blower motors
3509	4-2-21 replaced left center roller
3581	6-15-21 Changed engine oil & filter, air, fuel and cab filter. Changed final drive oil. Replaced tracks. Replaced fan and a/c belts. Replaced quick attach hoses. Repaired window frame.
2,226	9-1-21 replaced pivot pin on bobtach
	8/16/22 -Joplin E.S. - A/C not working. Found bad switch and thermostat. Replaced and tested ok.