

## Pillar To Post Home Inspectors

851 Nedvidek Street  
Cumberland, WI 54829

### Well Inspection

23567 25th St  
New Auburn, WI 54757  
11/08/2021

Prepared exclusively for:

**Bonnie Peterson**

Observations of the well system:

#### Drilled Well

- \* Well pump was functioning as intended.
- \* Pressure tank and associated components were functioning as intended.
- \* Water pressure maintained good flow with multiple fixtures running.
- \* Pressure tank maintained pressure during the test.
- \* The DNR sample faucet is missing according to the WI DNR standards this is considered a non-compliant feature. Immediate replacement is not required by the DNR.
- \* The home has two point (driven) well that is located in the basement. This is considered non-compliant according to the WI-DNR standards. If the home was built prior to 1953, the DNR may allow it to remain in service. The DNR states the following: When a well owner indicates that a basement well was installed on or before April 10, 1953 or under a building on or before to July, 1951, be advised that NR 812.42(1) states, "the owner shall provide written documentation verifying the date of construction or installation or both." It is the well owner's responsibility to prove the date of the installation. Without this proof, the DNR may conclude that the well is noncompliant and requires filling and sealing.

#### Results

The system is functioning, however the issues listed above need to be addressed to be compliant.

Water test results and WI DNR Well Form will be available in 3-5 business days.

Pump and Pressure Tank and Components



Inspection completed and composed by:

Andrew Morrison

POWTS License #1510188 WI DNR License #8989